LMA District Cover Sheet

Spring 2012 Levee Inspection Results

Sutter Maintenance Yard Maintenance Area 0017

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)				
	** Non-receipt of Su	ımmer or Winter Inspe	ection Reports may effec	ct overall annual rating.
* SPRING INSPECTIONS: Overall maintenance deficiencies are rated		nined for the spring ins ria in the spring and in		ual maintenance
FALL INSPECTIONS: The overall maintena within the attached u	ance rating shown abo nit inspection reports.	ve is based on operati	ion and maintenance de	ficiencies identified
Comments				

Unit Cover Sheet

Spring 2012 Levee Inspection Results

Sutter Maintenance Yard Maintenance Area 0017

Waterway	Bank	Unit Miles
Unit No. 01 Lake County Sutter Maintenance Yard - Middle Creek	Left	3.90

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	3/14/2012 - 3/14/2012			
DWR Inspector	Bob Duffey			
Accompanied By	Bryan Reniff Sutter Yard			

Summer & Winter Inspections

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

http://cdec.water.ca.gov/lma.html

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.

Levee Inspection Report By Mile - Spring 2012

Sutter Maintenance Yard Maintenance Area 0017

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Lake County Sutter Maintenance Yard - Middle Creek	Left	3.90	03/14/2012 03/14/2012	Bob Duffey

LMR	Levee	Mile	Catagoni	Item	Location	Rating	Action/Comment	GPS Latitud	e/Longitude	Issue No.
No.	Start	End	Category	item	tion	ing +	Action/Comment	Start	End	Photo
1			Earthen Levee	Operations & Maintenance Manuals	LS	A Ma		•	0	7
_								DWR ID: DWR_MA		
2			Earthen Levee	Emergency Supplies & Equipment		A Ma		0	0	8
								DWR ID: DWR_MA	A0017_01_s _ 2012	_8
3			Earthen Levee	Flood Preparedness & Training	LS	A Ma		0	0	9
				rrammig				DWR ID: DWR_MA	A0017_01_s _ 2012	_9
4	4.18	7.30	Earthen Levee	Trim / Thin Trees	WS	U Ma	T2 : Thin trees to allow visibility of the ground and room to flood fight.	39.142155 ° -122.902343 ° - DWR ID: DWR_MA		2 Y _2
5	4.18	7.31	Earthen Levee	Vegetation	WS	U Ma	V2 : Remove the wild growth other than native grasses from the levee slopes.	39.142155 ° -122.902343 ° - DWR ID: DWR_MA		1 Y _1
6	4.18	7.30	Earthen Levee	Vegetation	LS	A Ma	V1 : Control annual grass and weeds on the levee slopes and easements.	39.142155 ° 122.902343 ° DWR ID: DWR_MA	39.142155 ° 122.902343 ° ^{A0017} _01_s _ 2012	5 Y _5

Levee Inspection Report By Mile - Spring 2012

Sutter Maintenance Yard Maintenance Area 0017

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Lake County Sutter Maintenance Yard - Middle Creek	Left	3.90	03/14/2012 03/14/2012	Bob Duffey

Levee Mile Report Line	4
Start Levee Mile	4.18
End Levee Mile	7.30
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees
View of the trees on the Levee.	waterside slope of the

rduffey_s_20120312_343.jp	og
---------------------------	----

Levee Mile Report Line	5	
Start Levee Mile	4.18	
End Levee Mile	7.31	
Location	Water Side	
Category	Earthen Levee	
Item	Vegetation	
View of the six foot crown loves & heavy		

View of the six-foot crown levee & heavy vegetation on waterside slope.

rduffey_s_20120312_342.jpg

Levee Mile Report Line	6	
Start Levee Mile	4.18	
End Levee Mile	7.30	
Location	Land Side	
Category	Earthen Levee	
Item	Vegetation	
View of the native grasses on the landside slope and toe of the levee.		

rduffey_s_20120416_565.jpg







Location LS: Land Side WS : Water Side CR : Crown Rating

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monit

: Corrected : Acceptable but Monitor & Maintain

+ Issue Type

Ma: Maintenance Deficiancy
Ob: Design & System Obsolescence
En: Enforcement